

Work Order ID 145056

145056

Page 1

Monday, May 02, 2016 3:28:41 PM

Item ID: D350-561-241 Accept *N900040100* Setup Start *NS1*
 Revision ID: Stop *NS2*
 Item Name: Single Mirror Installation LH
 Start Date: 5/3/2016 Start Qty: 1.00 *1* Cust Item ID:
 Required Date: 5/5/2016 Req'd Qty: 1.00 *1* Customer:
 Reference:

Approvals: Process Plan: Em Date: 16/05/02 Tooling: _____ Date: _____
 QC: _____ Date: _____ SPC (Y/N): _____ Date: _____
 Run Start *NR1*
 Stop *NR2*

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
DSI 9564	A								
100	Document Control	00.00							
100	DOCUMENT CONTROL								
DC	Memo	0.00							
Doc.Control -USB or Paperwork	Photocopy bluefile and create labels per PPP D350-561-241	CHG001							
105	Pick Kit	0.00							
105									
Packaging	Memo	0.00							
Packaging									
110	QC4- 100% Inspect kits for completeness	0.00							
110									
QC	Memo	0.03							
Quality Control									

MAY 04 2016

DAS
28
9-89

MAY 05 2016

MAY 04 2016

DAS
27
9-89

DAS
28
9-89

MAY 05 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐																																																													
Date :		Step #:		QTY Effective :				MRB (QSI042) Approval																																																									
Description Work Order Deviation				Disposition				Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval																																																									
Root Cause		FAULT CATEGORY																																																															
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐	Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐	Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐	Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐	Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐	Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐	Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐	Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐	LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐	Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐	Past Expiry Date ☐	Manufacturing Process ☐	OTHER : _____			
Misidentified ☐	Past Due ☐																																																																

Work Order ID 145056

Monday, May 02, 2016 3:28:41 PM

145056

Page 2

Item ID: D350-561-241

Accept

N900040100Setup Start ***NS1***

Revision ID:

Stop ***NS2***

Item Name: Single Mirror Installation LH

Start Date: 5/3/2016 Start Qty: 1.00

1

Cust Item ID:

Required Date: 5/5/2016 Req'd Qty: 1.00

1

Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Run Start ***NR1***

QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
120		0.00							
120	Packaging								
Packaging	Memo	0.00							
Packaging	Identify and pack for shipping as per PPP D350-561-241 LOCATION: FG011 <i>PPP145054</i>								
130									
130	QC21- Final Inspection - Work Order Release	0.00							
QC	Memo	0.10							
Quality Control									

DAS
28
9-88

MAY 05 2016

MLJ

MAY 05 2016

MLJ

MAY 05 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QS1042) Approval 		
Description Work Order Deviation				Disposition					
							Completed By		
							Lead hand / Supervisor Approval Verification		
							QC / QA Coordinator Approval		

Root Cause				FAULT CATEGORY			
Environment ☐		No Re-verification ☐		Pressure/Forced ☐		Temperature/Cure ☐	
Design ☐		Operator ☐		Bending ☐		Set-up ☐	
Doc/Data ☐		Offset/Setup ☐		Centre Not Concentric ☐		BOM/Route ☐	
Equip/Tooling ☐		Supplier ☐		Cracks ☐		Broken/Damage/Defect ☐	
Handling/Pre ☐		Training ☐		Crimp/Kink/Ripple/Wave ☐		Inspection Incomplete/Unqualified ☐	
Material ☐		Use for Testing ☐		Cuffs ☐		Contamination ☐	
Internal Transport ☐		Poor Information ☐		Crushing ☐		Countersink ☐	
Tribal Knowledge ☐		Rushing ☐		Heat Treat ☐		Cut Too Short ☐	
LOA ☐		Product Improvement ☐		Wave/Twist in Tube ☐		Instructions Incomplete/Unclear ☐	
Substation ☐		Process Improvement ☐		Marks/Chatter ☐		Drill Holes ☐	
Past Expiry Date ☐		Manufacturing Process ☐		OTHER : _____			
Misidentified ☐		Past Due ☐					

Picklist Print

Monday, May 02, 2016 3:28:47 PM

Page 1

Work Order ID: 145056

145056

Parent Item: D350-561-241

D350-561-241

Parent Item Name: Single Mirror Installation LH

Start Date: 5/3/2016

Required Date: 5/5/2016

Start Qty: 1.00

Required Qty: 1.00

Comments: IPP revA 11.07.12 new issue EC verified by:JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
---------------------------------	------------------------	---------------	-------------	---------------------	------------------	-----------------	--------------------	----------------	-------------	--------------	---------------	----------------	--------

D2011-101		Manufactured	No				Each	11.0000		1			
D2011-101									**				
Mirror 6"													

DAS
28
9-89

Location	Loc Qty	Loc Code
FG	2	
106348	2	
ST384	9	
141126	9	

BAS
27
DAS 6 9-89

D2012-106		Manufactured	No				Each	25.0000		1			
D2012-106									**				
Arm													

DAS
28
9-89

Location	Loc Qty	Loc Code
st376	25	
105113	14	
105781	5	
135298	6	

BAS
27
DAS 6 9-89

D2012-107		Manufactured	No				Each	1.0000		1			
D2012-107									**				
Clevis													

DAS
28
9-89

Location	Loc Qty	Loc Code
WA004	1	
138845	1	

BAS
27
DAS 6 9-89

D2012-111		Manufactured	No				Each	19.0000		1			
D2012-111									**				
Bracket													

DAS
28
9-89

Location	Loc Qty	Loc Code
ST001	19	
112972	19	

BAS
27
DAS 6 9-89
MAY 04 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval		
Description Work Order Deviation				Disposition					
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐		Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐					
		OTHER : ☐							

Picklist Print

Page 2

Monday, May 02, 2016 3:28:47 PM

Work Order ID: 145056

145056

Parent Item: D350-561-241

D350-561-241

Parent Item Name: Single Mirror Installation LH

Start Date: 5/3/2016

Required Date: 5/5/2016

Start Qty: 1.00

Required Qty: 1.00

D2012-115

Manufactured No

Each

9.0000

1

DAS
6 27
9-89 9-89

D2012-115

Bracket, Clevis

DAS
28
9-89

Location

Loc Qty

Loc Code

ST001

9

136240

9

Each

89.0000

2

DAS
6 27
9-89 9-89

D2022-101

Manufactured No

D2022-101

Spacer

DAS
28
9-89

Location

Loc Qty

Loc Code

ST001

43

132703

43

ST012a

46

140201

46

Each

3.0000

1

DAS
6 27
9-89 9-89

D3629-1

Manufactured No

D3629-1

Bracket

DAS
28
9-89

Location

Loc Qty

Loc Code

ST047

3

137159

3

Each

1.0000

1

DAS
6 27
9-89 9-89

D3635-1

Manufactured No

D3635-1

Gasket

DAS
28
9-89

Location

Loc Qty

Loc Code

ST047

1

94552

1

MAY 04 2016

Monday, May 02, 2016 3:28:47 PM

Shop Packet Print

Page 2

DQA: _____ Date: _____

**WORK ORDER NON-CONFORMANCE / UPDATE**

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
OTHER : _____					

Picklist Print

Monday, May 02, 2016 3:28:47 PM

Page 3

Work Order ID: 145056

145056

Parent Item: D350-561-241

D350-561-241

Parent Item Name: Single Mirror Installation LH

Start Date: 5/3/2016

Required Date: 5/5/2016

Start Qty: 1.00

Required Qty: 1.00

D3646-2 Manufactured No

Each 4.0000 1

D3646-2

Arm

DAS
28
9-89

DAS
27
9-89

Location

Loc Qty

Loc Code

ST377

4

105082
105780

2

2

D3646-4 Manufactured No

Each 8.0000 1

D3646-4

Arm

DAS
28
9-89

DAS
27
9-89

Location

Loc Qty

Loc Code

ST377

8

106172
115775

2

6

D4070-041 Manufactured No

Each 12.0000 2

D4070-041

Clamp

DAS
28
9-89

DAS
27
9-89

Location

Loc Qty

Loc Code

ST076

12

124340
137228

1

11

AN3-5A Purchased No

Each 326.0000 6

****AN3-5A***

Bolt

DAS
28
9-89

DAS
27
9-89

Location

Loc Qty

Loc Code

FP001

26

m133686

2

m134055

24

ST350

300

m134502

300

Monday, May 02, 2016 3:28:47 PM

Shop Packet Print

Page 3

MAY 04 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐																																																											
Date :		Step #:		QTY Effective :				MRB (QS1042) Approval																																																							
Description Work Order Deviation				Disposition				Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval																																																							
Root Cause		FAULT CATEGORY																																																													
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐	Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐	Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐	Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐	Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐	Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐	Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐	Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐	LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐	Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐	Past Expiry Date ☐	Manufacturing Process ☐	OTHER : _____	
Misidentified ☐	Past Due ☐																																																														

Picklist Print

Monday, May 02, 2016 3:28:47 PM

Page 4

Work Order ID: 145056

Parent Item: D350-561-241

Parent Item Name: Single Mirror Installation LH

145056

D350-561-241

Start Date: 5/3/2016

Required Date: 5/5/2016

Start Qty: 1.00

Required Qty: 1.00

AN3-6A Purchased No

Each 210.0000 1

AN3-6A

Bolt

**

DAS 27
8 9-89

DAS
28
9-89

Location Loc Qty Loc Code

over003 175

M134630 75

M134654 100

ST349 35

M134055 35

Each 147.0000

3

**

DAS 27
8 9-89

AN4-5A Purchased No

AN4-5A

BOLT

DAS
28
89

Location Loc Qty Loc Code

CA 55

m129682 55

ST345 92

m134039 92

Each 74.0000

1

**

DAS 27
8 9-89 MAY 04 2016

AN4-10A Purchased No

AN4-10A

Bolt

DAS
28
9-89

Location Loc Qty Loc Code

CA 13

M129682 13

ST345 61

131677 5

M133234 56

Monday, May 02, 2016 3:28:47 PM

Shop Packet Print

Page 4

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval 		
Description Work Order Deviation				Disposition					
							Completed By		
							Lead hand / Supervisor Approval Verification		
							QC / QA Coordinator Approval		

Root Cause				FAULT CATEGORY							
Environment	☐	No Re-verification	☐	Pressure/Forced	☐	Temperature/Cure	☐	Power Loss/Surge	☐	Positioned Wrong	☐
Design	☐	Operator	☐	Bending	☐	Set-up	☐	Folio/Program	☐	Outside Dimensions	☐
Doc/Data	☐	Offset/Setup	☐	Centre Not Concentric	☐	BOM/Route	☐	Grain	☐	Over/Under tolerance	☐
Equip/Tooling	☐	Supplier	☐	Cracks	☐	Broken/Damage/Defect	☐	Weld	☐	Part Incorrect	☐
Handling/Pre	☐	Training	☐	Crimp/Kink/Ripple/Wave	☐	Inspection Incomplete/Unqualified	☐	Wrong Stock Pulled	☐	Part Lost/Missing	☐
Material	☐	Use for Testing	☐	Cuffs	☐	Contamination	☐	Out of Sequence	☐	Part Moved	☐
Internal Transport	☐	Poor Information	☐	Crushing	☐	Countersink	☐	Off-set	☐	Drawing	☐
Tribal Knowledge	☐	Rushing	☐	Heat Treat	☐	Cut Too Short	☐	Mislabeled	☐	Finish	☐
LOA	☐	Product Improvement	☐	Wave/Twist in Tube	☐	Instructions Incomplete/Unclear	☐	Fit/Function	☐	Misread	☐
Substation	☐	Process Improvement	☐	Marks/Chatter	☐	Drill Holes	☐	Misaligned/off center	☐	Turning Sequence	☐
Past Expiry Date	☐	Manufacturing Process	☐	OTHER : _____							
Misidentified	☐	Past Due	☐								

Picklist Print

Monday, May 02, 2016 3:28:47 PM

Work Order ID: 145056

145056

Parent Item: D350-561-241

D350-561-241

Parent Item Name: Single Mirror Installation LH

Start Date: 5/3/2016

Required Date: 5/5/2016

Start Qty: 1.00

Required Qty: 1.00

NAS1149D0363J

Purchased

No

Each

2,319.000

8

NAS1149D0363.J

Washer

DAS 6 27
9-89 9-89

DAS
28
9-89

Location

Loc Qty

Loc Code

GA

518

m134055

518

ST260a

1000

m134676

1000

ST263

801

m134606

801

Each

2,724.000

8

NAS1149D0463J

Purchased

No

NAS1149D0463.J

WASHER

DAS
28
9-89

Location

Loc Qty

Loc Code

GA

328

M132035

21

M134508

307

ST260a

1000

M134634

1000

ST263

408

M134039

29

M134508

302

M134573

77

ST269

988

M132317

100

M132677

888

DAS 6 27
9-89 9-89

MAY 04 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐																																																											
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval																																																								
Description Work Order Deviation				Disposition				Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval																																																							
Root Cause		FAULT CATEGORY																																																													
Environment ☐	Design ☐	Doc/Data ☐	Equip/Tooling ☐	Handling/Pre ☐	Material ☐	Internal Transport ☐	Tribal Knowledge ☐	LOA ☐	Substation ☐	Past Expiry Date ☐	Misidentified ☐	No Re-verification ☐	Operator ☐	Offset/Setup ☐	Supplier ☐	Training ☐	Use for Testing ☐	Poor Information ☐	Rushing ☐	Product Improvement ☐	Process Improvement ☐	Manufacturing Process ☐	Past Due ☐	Pressure/Forced ☐	Bending ☐	Centre Not Concentric ☐	Cracks ☐	Crimp/Kink/Ripple/Wave ☐	Cuffs ☐	Crushing ☐	Heat Treat ☐	Wave/Twist in Tube ☐	Marks/Chatter ☐	Temperature/Cure ☐	Set-up ☐	BOM/Route ☐	Broken/Damage/Defect ☐	Inspection Incomplete/Unqualified ☐	Contamination ☐	Countersink ☐	Cut Too Short ☐	Instructions Incomplete/Unclear ☐	Drill Holes ☐	Power Loss/Surge ☐	Folio/Program ☐	Grain ☐	Weld ☐	Wrong Stock Pulled ☐	Out of Sequence ☐	Off-set ☐	Mislabeled ☐	Fit/Function ☐	Misaligned/off center ☐	Positioned Wrong ☐	Outside Dimensions ☐	Over/Under tolerance ☐	Part Incorrect ☐	Part Lost/Missing ☐	Part Moved ☐	Drawing ☐	Finish ☐	Misread ☐	Turning Sequence ☐
																								OTHER : ☐																																							

Picklist Print

Page 6

Monday, May 02, 2016 3:28:47 PM

Work Order ID: 145056

145056

Parent Item: D350-561-241

D350-561-241

Parent Item Name: Single Mirror Installation LH

Start Date: 5/3/2016

Required Date: 5/5/2016

Start Qty: 1.00

Required Qty: 1.00

MS21042L3

Purchased

No

Each

1,830.000

4

DAS

MS21042L3

DAS
6
9-89

DAS

Nut

27

9-89

DAS
28
9-89

Location

Loc Qty

Loc Code

FP001

100

m133790

100

GA

713

m133790

3

m134360

710

ST303

1017

m134039

12

m134360

405

m134634

600

4

MS21042L4

Purchased

No

Each

1,848.000

4

MS21042L4

DAS

Locknut

27

9-89

DAS
28
9-89

Location

Loc Qty

Loc Code

GA

279

m133769

279

OVER007

500

m134676

500

ST303

972

m134606

972

ST305

97

m130922

97

4

DAS
6
9-89

MAY 11 2016

Monday, May 02, 2016 3:28:47 PM

Shop Packet Print

Page 6

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :				MRB (QS1042) Approval	
Description Work Order Deviation				Disposition					
								Completed By	
								Lead hand / Supervisor Approval Verification	
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐							
		OTHER : ☐							

REFERENCE ONLY

5. PARTS LIST

Qty -041	Qty -043	Qty -045	Qty -141	Qty -143	Qty -241	Qty -243	Part Number	Description
X	1						D350-561-041	SINGLE MIRROR INSTALLATION, RH
	X						D350-561-043	DUAL MIRROR INSTALLATION, RH
	1	X		1		1	D350-561-045	MIRROR KIT
			X	1			D350-561-141	SINGLE MIRROR INSTALLATION, RH
				X			D350-561-143	DUAL MIRROR INSTALLATION, RH
					X	1	D350-561-241	SINGLE MIRROR INSTALLATION, LH
						X	D350-561-243	DUAL MIRROR INSTALLATION, LH
1		1	1		1		D2011-101	Mirror
1							D2012-101	Arm
1							D2012-103	Arm
1			1				D2012-105	Arm
					1		D2012-106	Arm
2			1		1		D2012-107	Clevis
1							D2012-109	Bracket
1			1		1		D2012-111	Bracket
4		2					D2012-113	Clamp
1			1		1		D2012-115	Bracket
4			2		2		D2022-101	Spacer
4							D2856-100-325	Abrasion Strip
1*		1*	1*		1*		D3014-1	Locknut
			1		1		D3629-1	Bracket
			1		1		D3635-1	Gasket
		2					D3635-3	Gasket
			1				D3646-1	Arm
					1		D3646-2	Arm
			1				D3646-3	Arm
					1		D3646-4	Arm
			2		2		D4070-041	Clamp
2							AN3-4A	Bolt
2		2	6		6		AN3-5A	Bolt
1			1		1		AN3-6A	Bolt
2			1		1		AN4-10A	Bolt
3			3		3		AN4-5A	Bolt
14		4	8		8		AN960JD10	Washer
9		2	8		8		AN960JD416	Washer
1*		1*	1*		1*		AN960JD416L	Washer
5		2	4		4		MS21042L3	Nut (or MS21042-3)
5			4		4		MS21042L4	Nut (or MS21042-4)

*INCLUDED AS PART OF D2011-101 MIRROR